



The QRMax System is designed for rapid mount and dismount of Wheels, Yokes and Throttle Quadrants to and from your rig

Note: you will need a QRMax Base Plate to use this adapter.

Fitting the QRMax VirtualFly V3RNIO+ Plate to your VirtualFly V3RNIO+ Controller

 Identify the 4x M4 threaded mounting holes on the base of your VirtualFly V3RNIO/V3RNIO+ highlighted here in RED





- First attach the Adapter Plate to the base of the VirtualFly V3RNIO/V3RNIO+ using the 4x M4x14mm (smaller) screws provided. Note the orientation

Tighten to the pinch + 1/16th turn.

- Next, attach the QRMax QR Plate to the Adapter Plate using the 4x M6x16mm Screws provided. Note the orientation.

- Tighten to the pinch, do not overtighten and take care not to cross the threads to avoid damaging the plastic.

If you require further support, please used the <u>contact form on our website</u>, or email us directly <u>support@qr4rigs.com</u>, we will be more than happy to help you.